



NOTES:-

- 1. REMOVE ALL SHARP EDGES.
- 2. ALL DIMENSION TOLERANCE $\pm 0.1\text{mm}$ OTHERWISE SPECIFIED.
- 3. AFTER EXTRUSION CLEAR ANODIZED 10 - 20 MICRONS