

F



REMOVE SHARP CORNERS WITH 0.30mm R.

1. Surface even and closed
2. Trim edges should be clear from sharp cuts
3. Part should be free from oil, chips and other contaminations
4. Critical dimensions are marked with *
5. Unspecified radius: 0.1 – 0.3mm
6. Unspecified chamfer: 0.1 x 45°

UNLESS OTHERWISE SPECIFIED:
DIMENSIONS ARE IN MILLIMETERS
SURFACE FINISH:
TOLERANCES:
LINEAR:
ANGULAR:

A

AREA: 1312.135	Sq mm
WEIGHT: 3.543	kg/m
INNER PERIMETER:	mm
OUTER PERIMETER: 412.61	mm
LENGTH:	$\begin{matrix} +10 \\ -0 \end{matrix}$ mm
FINISH: MILL FINISH	