


Q42567

due to thickness variation we may get impression mark at these places



semi-hollow die a small projection mark may appear in these places