


Q02983



DUE TO THICKNESS VARIATION,
 WE MAY GET IMPRESSION MARK

ALL SCREW BULB WILL BE 60° OPEN