

Φ02379

ALLOY-6061T6

Ø425 x 225 Thick + Bolster

51mm thickness in mm in 6061T6 Alloy
we can give in 6063 Alloy since thickness is
very high. fusion Bonding problem will be
there in high lighted area.

